

## Service Bulletin

17-012

June 24, 2017 Version 1

## Product Update: 2015–16 TLX 9-Speed Transmission Warmer (Transmission Previously Replaced for Transmission Warmer Leaking)

You may have received tools for this service bulletin. Please save the tools and store them in a safe place for this upcoming market action.

Refrain from calling Tech Line for updates. This placeholder will be updated as information becomes available along with an updated iN message.

**CLIENT INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.