



# SERVICE BULLETIN

|                             |                         |                            |
|-----------------------------|-------------------------|----------------------------|
| Classification:<br>BR16-004 | Reference:<br>NTB16-116 | Date:<br>November 28, 2016 |
|-----------------------------|-------------------------|----------------------------|

## NISSAN; DIAGNOSIS INFORMATION FOR ABS DTC C1130

|                          |                               |                                    |
|--------------------------|-------------------------------|------------------------------------|
| <b>APPLIED VEHICLES:</b> | 2013-2017 Altima Sedan (L33)  | 2017 Titan (A61)                   |
|                          | 2012 Altima Coupe (L32)       | 2012 Sentra (B16)                  |
|                          | 2012-2014 Maxima (A35)        | 2013-2017 Sentra (B17)             |
|                          | 2016-2017 Maxima (A36)        | 2012-2013 Versa Hatchback (C11)    |
|                          | 2012-2014 Murano (Z51)        | 2012-2017 Versa Sedan (N17)        |
|                          | 2015-2017 Murano (Z52)        | 2014-2017 Versa Note (E12)         |
|                          | 2016-2017 Murano Hybrid (Z52) | 2012-2017 Frontier (D40)           |
|                          | 2012 Pathfinder (R51)         | 2012-2017 Quest (E52)              |
|                          | 2013-2017 Pathfinder (R52)    | 2012-2017 Juke (F15)               |
|                          | 2014 Pathfinder Hybrid (R52)  | 2014-2017 NV Cargo/Passenger (F80) |
|                          | 2012-2013 Rogue (S35)         | 2013-2017 NV200 (M20)              |
|                          | 2014-2015 Rogue Select (S35)  | 2014-2017 Taxi                     |
|                          | 2014-2017 Rogue (T32)         | 2012-2015 Armada (TA60)            |
|                          | 2017 Rogue Hybrid (T32)       | 2017 Armada (Y62)                  |
|                          | 2012-2015 Titan (A60)         | 2012-2017 370Z (Z34)               |
|                          | 2016-2017 Titan XD (A61)      |                                    |

### SERVICE INFORMATION

When diagnosing for DTC C1130 (ENGINE SIGNAL): ECM related DTCs (P-codes) must be diagnosed, repaired, and DTCs erased first.

- DTC C1130 is an ABS DTC that indicates an output signal of the ECM is not recognized.
- Absent or incorrect ECM signals, that are indicated by corresponding P-codes, may trigger C1130 in the ABS control unit.
- Some vehicle features that can be affected by absent or incorrect ECM signals are:
  - Forward Emergency Braking (FEB)
  - Intelligent Cruise Control (ICC)
  - VDC/ABS/TCS

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.