

# Technical Service Bulletin



## 94 Headlight switch pressed in

94 15 66 2017566/5 April 17, 2015. Supersedes Technical Service Bulletin Group 94 number 13-12 dated March 29, 2013 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3, A4, A5, A5 Cabriolet, A6, A7, A8, Q5	2012 - 2017	All	Not Applicable

## Condition

REVISION HISTORY		
Revision	Date	Purpose
5	-	Revised header data (Added models and model years) Revised <i>Technical Background</i> (Added photos)
4	3/29/2013	Revised header data (Added model years and A6/A7)
3	8/12/2009	Revised header data (Added A5 Cabriolet and Q5, new customer code)

The headlight switch knob is pressed in, but the switch functions correctly.

## Technical Background

The headlight switch knob was designed with a normal position and a pushed-in position (Figure 1, Figure 2, and Figure 3). This feature was designed to avoid injuries during a collision.



**Figure 1.** B8 headlight switch knob pushed in (left) and in normal position (right).



**Figure 2.** A3 headlight switch knob pushed in (left) and in normal position (right).



**Figure 3.** A6 and A7 headlight switch knob pushed in (left) and in normal position (right).

## Production Solution

Not applicable.

## Service

1. Pull out the knob and return it to the original position.
2. Explain the *Technical Background* to the customer.

## Warranty

This TSB is informational only and not applicable to any Audi warranty.

# Technical Service Bulletin

---



## Additional Information

All parts and service references provided in this TSB (2017566) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.