On-car analysis list from June 26th, 2014 please contact VW Helpline before attempting repair

| | Models | MY | Engine | Transmission | Торіс | Customer Complaint |
|------------|-----------------------------------|-----------|---|--------------|--|---|
| Powertrain | Touareg, Beetle, Jetta, Passat | 2014-2015 | 1.4T, 1.8T, 2.0L (Jetta ONLY), 2.0T, 2.5L (Jetta ONLY), 3.0L | All | EVAP leak / EVAP circuit related faults, perform GFF, if GFF fails or does not provide a resolution contact the VW Technician Helpline | MIL-on |
| ybc | Jetta | 14 | All | All | Car -Net Button | Car-Net button fell into the overhead console housing |
| B | Jetta | 14 | All | All | Sunroof glass panel misaligned causing wind noise concern | Wind noise from sunroof |
| Electrical | No Current Topics | | | | | |
| Chassis | No Current Topics | | | | | |