

JTB00573NAS1

# TECHNICAL BULLETIN

04 AUG 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

## INFORMATION

---

## SECTION:

501-18: Folding Top

---

**SUBJECT/CONCERN:**

Removable Rear Quarter Window Securing Pin Modification

---

**AFFECTED VEHICLE RANGE:**

<b>MODEL:</b>	<b>MODEL YEAR:</b>	<b>VIN:</b>	<b>ASSEMBLY PLANT:</b>	<b>APPLICABILITY:</b>
F-TYPE (X152)	2016	K24802- K31384	Castle Bromwich	Folding Top

---

**MARKETS:**

NORTH AMERICA

---

**CONDITION SUMMARY:**

**Applicable to F-TYPE Project 7 vehicles only.**

**SITUATION:**

When installing the removable rear quarter window to the vehicle, it may be difficult to operate the locking lever.

**CAUSE:**

This may be caused by insufficient length locking pin.

**ACTION:**

Should a customer express this concern, follow the Service Instruction below.

---

**PARTS:**

PART NUMBER	DESCRIPTION	QUANTITY:
T2R25490	Pin kit	1

---

**TOOLS:**

Refer to Workshop Manual for any required special tools.

---

**WARRANTY:**
**NOTES:**

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.
- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Removable rear quarter window securing pin - Modification	76.96.54	0.1	42	T2R25490

**NOTE:**

Normal Warranty procedures apply.

**SERVICE INSTRUCTION:**


---

- 
- 1 Replace the removable rear quarter window securing pin (see TOPlx Workshop Manual section 501-18: Folding Top - Removable Rear Quarter Window Securing Pin - Project 7).