

Technical Service Bulletin



01 MIL on (DTC P0456) - Repair Authorization

01 15 10 2039888/1 February 23, 2015.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7	2015	All	3.0T

Condition

- MIL on.
- **DTC P0456** (very small EVAP leak) stored in engine control module (ECM), J623 (address word 01).
- There is no leak in the EVAP system.

Technical Background

Various parts have been replaced under warranty for the condition noted above, but no issues were identified with these parts. In an effort to gain information on the condition, we are asking that you contact the Audi Technical Assistance Center (TAC) before replacing any parts. This will assist us in diagnosing any potential issues.

Production Solution

No changes to production have been made, as no issue has been identified.

Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.

1. Verify the condition.
2. If the vehicle is within the New Vehicle Limited Warranty, contact a TAC consultant before proceeding. Attach the DTC and diagnostic log to the TAC ticket.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

Technical Service Bulletin



All parts and service references provided in this TSB (2039888) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.