

**On-car analysis list from July 25th, 2014  
please contact VW Helpline before attempting repair**

	<b>Models</b>	<b>MY</b>	<b>Engine</b>	<b>Transmission</b>	<b>Topic</b>	<b>Customer Complaint</b>
<b>Powertrain</b>	Touareg, Beetle, Jetta, Passat	2014-2015	1.4T, 1.8T, 2.0L (Jetta ONLY), 2.0T, 2.5L (Jetta ONLY), 3.0L	All	EVAP leak / EVAP circuit related faults, perform GFF, if GFF fails or does not provide a resolution contact the VW Technician Helpline	MIL-on
<b>Body</b>	Jetta	14	All	All	Car -Net Button	Car-Net button fell into the overhead console housing
	Jetta	2014	All	All	Front windows binding during operation causing false pinch protection activation or noise while operating the window.  VIN range EM236581 to EM350000 or EM386721 to EM500000	Front window(s) binding or noise during operation
	Jetta	14	All	All	Sunroof glass panel misaligned causing wind noise concern	Wind noise from sunroof
<b>Electrical</b>	Passat	13 - 14	All	All	Speaker sounds abnormal (rattles, buzzes, distorts, sounds "blown", crackles, muffled). Non-Fender Audio Systems only. Contact Technical Helpline prior to performing any disassembly or repair.	Speaker sound abnormal (rattles, vibrates, crackles, distorts, sounds "blown").
<b>Chassis</b>	No Current Topics					