



Technical Journal

TITLE:

Outer rear view mirror folding function, intermittently not folding

REF NO: TJ 30848	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2016-05-20	STATUS DATE: 2016-05-26
FUNC GROUP: 8460	FUNC DESC: Outside mirrors	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256							2016-9999		0000561-9999999	201505-999952

CSC Customer Symptom Codes

Code	Description
XP	Door mirrors/Folding does not work

VST Operation Number

VST Operation Number	Description
36004-2	Software download

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

**DESCRIPTION:**

*TJ= Technical Journal

Customer may intermittently experience the vehicle ORVM (outer rear view mirror) will not fold when locking/unlocking.

SERVICE:

*Follow TJ 31543

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support Not Needed", use function group 8460.