

PROFI Dealer Outbound Information Request Form

MY(s) Affected:	2015-2016	Issue ID #	2015-047
Vehicle Model(s):	Golf SportWagen	Photos (if applicable):	
VIN Range (if applicable):	All		
Engine Code(s):	All		
Gearbox (Manual / Automatic):	All		
Issue Description / Symptom:			
Water leak from sunroof / water stains on headliner.			
Workshop Problem Validation Procedure:			
Inspect vehicle for loose or pinched sunroof drain tubes.			
Required Actions:			
If a loose or pinched sunroof drain tube is found to be the cause of the complaint, please obtain pictures showing the condition of the sunroof drain tube and the location of the pinched/disconnected drain on the vehicle. Please send pictures and vehicle information in to the Profi inbox with the title "2015-047 Golf SportWagen Sunroof Drain Tube."			
Please repair the vehicle as needed.			
VWoA Contact Information:			
Requestor:	Jeff Zimmerman		
E-mail:	jeffrey.zimmerman@vw.com		
Phone Number:	248-754-4340		
Alternative Contact:	Kevin Lentzer		
E-mail:	kevin.lentzer@vw.com		
Phone Number:	248-754-5901		