

57 Various features in the rear passenger compartment are inoperative

57 13 94 2035367/1 September 25, 2013.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All	2003 - 2015	All	Not Applicable

Condition

Various features in the rear passenger compartment are inoperative. Some features may include power rear windows, rear climate control operating unit, rear sunroof panel, rear reading lamps, rear cigarette lighters, etc.

Technical Background

By design, many electronically-controlled features in the rear passenger compartment, in addition to the power rear windows, are deactivated if the child lock in the driver's door is activated.

Production Solution

Not applicable.

Service

Before diagnosing a customer complaint of an inoperative feature in the rear passenger compartment, make certain that the inoperative feature is not due to an activated child lock system.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All parts and service references provided in this TSB (2035367) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2013 Audi of America, Inc.

Page 1 of 1

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.