GPOP - Issue Review System

Part Number: 68211202A\$

Part Description: Water Pump

Issue Dealers are replacing water pumps because of a coolant leak. Water pumps are Description: found TNF but the water pump bypass o-ring was pinched resulting in a coolant leak that looks like a failed pump. Please inspect the bypass o-ring before replacing the

pump as it is available separate for service.

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.