



Volkswagen

Warranty Information

General Communication

Number: VWC-17-02

Subject: Cable Connection is Required for the Emissions Recall
23Q3 Software Update

Date: Feb. 6, 2017

This document conveys
Volkswagen Warranty general
information.

Cable Connection is Required between the VAS 6150X Tester and the VAS 5054A Transmitter Head for the Emissions Recall 23Q3 Software Update

This communication is a reminder that a **cable connection** is **required** when performing the 23Q3 emissions recall software update.

Points to Remember

- ▶ VAS6150X diagnostic tester or equivalent must be updated with the most current ODIS Service application and diagnostic content version prior to performing any Software Version Management update
- ▶ Dealers **must** always “hardwire with a USB cable connection” (not a Wi-Fi or Bluetooth connection) between the VAS 6150X Tester and the VAS 5054A Transmitter Head
- ▶ Wi-Fi or Bluetooth connection between the VAS 6150X Tester and the VAS 5054A Transmitter Head is **prohibited**, and can be traced by Volkswagen of America
- ▶ Claims for ECM/TCM failure or other consequential component failure resulting from a Wi-Fi or Bluetooth connection error during this update will be rejected for payment

ODIS Screens Showing Connection Type



ODIS screens showing connection type. Do not perform the update while using a Wi-Fi or Bluetooth connection (left images). A cable connection must be used (right image).

Questions

For any questions regarding this communication, please contact the Warranty Helpline at 1-866-306-8447 or warranty.helpline@vw.com.