



Technical Bulletin

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta, Beetle, Beetle Convertible	2013-2015	2.0T (CPPA, CPLA)	All	All	All
Jetta, Passat, Beetle, Beetle Convertible	2014-2015	1.8T (CPKA, CPRA)	All	All	All
GTI	2015	2.0T (CXCA, CXCB)	All	All	All
GTI	2015	2.0T (CNTA)	All	All	All
Golf	2015	1.8T (CNSB, CNSA)	All	All	All
Golf, Golf SportWagen,	2015	1.8T (CXBA, CXBB)	All	All	All

Condition

24 15 03 April 6, 2015 2040179 Supersedes Technical Bulletin V241502 dated March 24, 2015 to include additional engine applicability.

DTC P2014 Intake Manifold Position Sensor -G336- Replacement

Direction on proper part replacement when diagnosing fault code P2014 in the ECM.

Technical Background

Information only.

Production Solution

Information only.



Technical Bulletin

Service

If after performing Guided Fault Finding (GFF) for fault code P2014 in the ECM, the Intake Manifold Runner Position Sensor -G336- requires replacement, only replace the sensor, NOT the entire intake manifold assembly. Claims for intake manifolds will be debited unless directed and documented by GFF.



Note:

When claiming Intake Manifold Runner Position Sensor -G336- use PID 2465.

Warranty

Information only.

Required Parts and Tools

Information only.

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.