

Technical Bulletin

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All	2013-2016	All with TDI	All	All	All

Condition

23 15 01 June 24, 2015 2041118

Diesel Fuel System Diagnoses and Repair

One or more of the following fault codes may be stored in the ECM Fault Memory:

DTC	Description
P0087	Fuel Rail/System Pressure – Too Low
P0088	Fuel Rail/System Pressure – Too High
P0191	Fuel Rail Pressure Sensor “A” Circuit Range/Performance

Technical Background



Note:

These vehicles are not covered by the Warranty Extension found within Policies and Procedure Bulletin VWP-15-06.

Production Solution

Information Only.

Service

For diagnostic and repair information, please see Technical Bulletin 2041063 (V231503).



Tip:

Google search must be used to locate Technical Bulletin 2041063.

Technical Bulletin

Warranty

Warranty covers the replacement of diesel fuel system components **only** if:

- The vehicle has a Volkswagen-approved misfueling guard installed **and**
- The correct, uncontaminated fuel is present in the vehicle.

Please use appropriate labor operations from ELSA and parts from ETKA based on vehicle type.

Active VW Customer Mobility Program (VWCMP) loaner vehicles are eligible to receive \$35 per day for loaner expense reimbursement under warranty (refer to document VWS-14-03 for applicable labor operation).



Note:

This bulletin is for informational purposes only if the vehicle is outside of warranty coverage.

Required Parts and Tools

No Special Parts required.

Tool Description	Tool No:
Midtronics Battery Tester/Charger	InCharge 940 (INC-940) or GRX3000VAS
VAS Diagnostic Tool	VAS 6150/X & VAS 6160/X with - ODIS Service with: current online updates

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.