

Technical Service Bulletin



46 MY15 Pulsation while braking at speeds above 50mph - Repair Authorization

46 14 97 2039005/1 November 18, 2014.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
RS5	2015	All	4.2L
RS5 Cabriolet	2015	All	4.2L
R8	2015	All	All
A8	2015	All	3.0T, 4.0T, & TDI (w/o W12 & S8)
A6, A7	2015	All	3.0T

Condition

Pulsation from the front brakes while braking at speeds above 50 mph.

Technical Background

In an effort to gain information on the condition listed above, we are asking that you contact the Audi Technical Assistance Center (TAC) before performing any repairs. This will assist us in diagnosing any potential issues with the condition noted above.

Production Solution

No changes to production have been made, as no issue has been identified.

Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.

1. Verify the condition.
2. If the vehicle is within the New Vehicle Limited Warranty, contact a TAC consultant before proceeding.



Tip: Repairs performed without a TAC ticket will be denied.

Technical Service Bulletin



Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All parts and service references provided in this TSB (2039005) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.