

Technical Service Bulletin



01 MIL on (DTC P033100 or P033200) in ECM - Repair Authorization

01 13 88 2033766/1 May 2, 2013.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6/A7	2012-2013	All	3.0 FSI Engine

Condition

- MIL on.
- One or both of the following DTCs are stored in the engine control module, J623 (address word 01):
 - **DTC P03300** (Knock Sensor 2 Circuit Range/Performance)
 - **DTC P033200** (Knock Sensor 2 Circ. Low Input)

Technical Background

Not applicable.

Production Solution

No changes in production have been made, as no issues have been identified.

Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.

1. Verify that **DTC P033100** and/or **DTC P033200** is stored in memory.
2. Do **not** disconnect any connectors and **do not** delete the DTCs.
3. Contact a TAC consultant before proceeding.
4. Attach the DTC and diagnostic log to the TAC ticket.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Technical Service Bulletin



Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.