ACURA ServiceNews Article

January 2018

B18010I Version 1

Navigation Screen Clock Reads 00:00

AFFECTED VEHICLES

2001-03 CL, 2001-02 MDX, 2000-03 RL, and 2000-03 TL

Is the navigation screen clock reading 00:00? We're aware of this issue and have it under investigation.

For models that **didn't** have the navigation maps updated with software **Version 2.1x to 2.Ax**, this issue self-corrected on **September 17, 2017**, and the clock reads normally. For models that **did** have the navigation maps updated with that software version, this issue remains and the clock reads **00:00**.

We're currently working on a software patch to fix this.

© 2018 American Honda Motor Co., Inc. – All Rights Reserved