

Reference	SSM73542
Models	F-PACE / X761 F-TYPE / X152 XE / X760 XF / X260
Title	Ingenium I4 2.0L Petrol Turbo Actuator Arm Rattle
Category	Engine
Last modified	04-Sep-2017 00:00:00
Symptom	497000 Engine Noise

Content **Issue:** Rattle noise from turbo waste gate actuator which is more evident from engine cold start but also when engine is under slight load and on overrun.

Cause: Excess play within the turbo waste gate actuator arm.

Action: JLR are currently investigating solutions for this concern and the retailer repair will be released in due course. It must be noted that there is no functionality or durability effect on the vehicle.

Please note: Under no circumstances should the turbo be replaced for this concern.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.