



Technical Journal

TITLE:

**DTC BECM-P060A00 Internal Control Module Monitoring
Processor Performance**

| | | | |
|--|---|--|-----------------------------------|
| REF NO: TJ 33070.1.0 | ISSUING DEPARTMENT: Technical Service | CAR MARKET: United States and Canada | |
| PARTNER: 3 US 7510 Volvo Car USA | | ISSUE DATE: 2017-10-04 | STATUS DATE: 2017-10-09 |
| FUNC GROUP: 3113 | FUNC DESC: Battery, high voltage | Page 1 of 2 | |

“Right first time in Time”

Attachment

Vehicle Type

| Type | Eng | Eng Desc | Sales | Body | Gear | Steer | Model Year | Plant | Chassis range | Struc Week Range |
|------|-----|----------|-------|------|------|-------|------------|-------|-----------------|------------------|
| 246 | BR | B1FPHEV | | | | | 2018-2018 | | 0000025-0017029 | 201717-201739 |
| 256 | BC | B1BPHEV | | | | | 2016-2018 | | 0008280-0321806 | 201526-201739 |
| 256 | BR | B1FPHEV | | | | | 2018-2018 | | 0008280-0321806 | 201717-201739 |

CSC Customer Symptom Codes

| Code | Description |
|------|---|
| FB | Text window and warning symbol/Other problems |

VST Operation Number

| VST Operation Number | Description |
|----------------------|-------------------------------------|
| 36004-2 | Software control module downloading |

DTC Diagnostic Trouble Codes

| Control Module | Code | Fault Type |
|----------------|---------|--------------|
| BECM | P060A00 | Intermittent |

Text

**DESCRIPTION:**

DTC BECM-P060A00 may appear when performing VIDA read out. If the DTC is present please follow step under Service.

Reported symptoms are:

- Error message in DIM

BECM = Battery Energy Control Module

DIM = Driver Information Module

SERVICE:

Perform an upgrade of the software according to TJ 31543.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support needed", use function group 3113.