



# Technical Service Bulletin

---

**01 V6 TDI - DTC P026300, P026600, P026900, P027200, P027500, P027800 with DFCC 19184, 19185, 19186, 19187, 19188, 19189**

01 17 15 2047785/1 May 16, 2017.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8	2014 – 2016	All	V6 TDI
Q7	2013 - 2015	All	V6 TDI
A6, A7, Q5	2014 – 2016	All	V6 TDI

## Condition

### Customer concern:

- MIL on.

One or more of the following DTCs are stored in the engine control module, J623 (address word 0001) **only** with a DFCC/symptom code between 19184 and 19189:

- **DTC P026300** (Cylinder 1 Contribution/Balance)
- **DTC P026600** (Cylinder 2 Contribution/Balance)
- **DTC P026900** (Cylinder 3 Contribution/Balance)
- **DTC P027200** (Cylinder 4 Contribution/Balance)
- **DTC P027500** (Cylinder 5 Contribution/Balance)
- **DTC P027800** (Cylinder 6 Contribution/Balance)
- Faults are NOT in conjunction with a high pressure fuel pump failure, misfuel, or contaminated fuel scenario. In such a case, the TSB would not apply.

## Technical Background

Audi of America is requesting your cooperation in supplying us with technical information regarding the above condition, we are asking that you contact the Audi Technical Assistance Center (TAC) before replacing any parts. This will assist us in diagnosing any potential issues with the customer concern.

## Production Solution

No changes to production have been made, as no issue has been identified.



# Technical Service Bulletin

---

## Service

Diagnosis and repair information will be given on a case by case basis by the Audi Technical Assistance Center (TAC).

## Warranty

This TSB is informational only and not applicable to any Audi Warranty.

## Additional Information

All parts and service references provided in this TSB (2047785) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.