



## Technical Information Bulletin

---

**18-008**



### **Section**

Hubs-Wheels - 18

---

### **Subject**

Steer Axle Hubcap Leak

---

### **Release Date**

1/22/2018

---

### **Condition**

Leak from steer axle hubcap plug.

---

### **Chassis Affected**

T680/T880, T800, W900, T660, T440/T470, and T170/T270/T370 vehicles built from 4/21/2014 through 8/01/2017 with Dana D2000/D2200/D1600, Meritor MFS 20/MFS 22, or FL941 steer axles equipped with ConMet PreSet Plus Hubs.

---

### **Action**

#### **FIX-AS-FAIL**

If a customer comes into your dealership and demonstrates the condition above, replace the hubcap plug. Use the procedure below.

---

## Warranty

Through Standard Warranty (excludes Extended Warranty) Kenworth will pay for parts at dealer net plus applicable mark-up and labor:

- 0.3 hours labor to R&R 2 hubcap plugs. Use Quick Claim code 18-008.
- File an additional claim for extraordinary circumstances. A quick claim for standard labor must be filed first.

**Take-Off Parts Disposition: Destroy take-off parts after claim is paid**

CLAIM CODING			
Failure Location:	018-003-018	Work Accomplished:	35
Failure Type:	235	Responsibility Code:	01
SRT Code:	018-110	Claim Type:	N
Vendor Code:	04088AB		

## Parts

Parts are available from PACCAR Parts.

Quantity	Part Number	Description
2	CM10080777	Plug, Hubcap

## Procedure

Remove and replace both steer axle hubcap plugs.

Authored by: OF

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2018 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact the [DealerNet Webmaster](#).