

TOL NOTICE (US&CAN) – January 23, 2018

New Diagnostic Software Available for Download

Diagnostic software version **2018-1** is now available to download. Dealers should download this update from your Triumph Diagnostic Software page under the Service/Technical menu and begin using immediately.

- Please ensure all new bikes have the latest software downloaded at PDI.
- Please ensure all bikes being serviced have the latest software downloaded.
- Please ensure all relevant staff are informed of this update.



Important Note: We must confirm that dealers have downloaded this latest software update before delivery of any new 2018 Tiger 1200 models. Please take a moment to complete the following confirmation form following successful software download:

[\[Diagnostic Software Download Confirmation\]](#)

PASSWORD: No change to password: (case sensitive) Cafe1902

SUMMARY OF CHANGES:

1	New Software Functionality:	Updated chassis ECM download process for Tiger 1200 models
2	New Calibrations:	None
3	Replacement Engine Calibrations:	None
4	Replacement Chassis Calibrations:	Tiger 1200 models
5	Replacement Instrument Calibrations:	2018 Bonneville Speedmaster
6	New ECU Unlock Codes:	2018 Bonneville Speedmaster 27177146
7	Calibration Description Corrections:	None
8	Bug Fix(es):	None

If you have any questions, please contact Triumph 24/7 Customer Support at (888) 284-6288.

TRIUMPH MOTORCYCLES AMERICA