



Technical Service Bulletin

Technical Service Bulletin: TSB180017	Released Date: 31-Jan-2018
Racor® Fuel Filter Plugging on Navistar® Chassis	

Racor® Fuel Filter Plugging on Navistar® Chassis

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Information Only - OEM Related Matter Not Covered By Cummins® - Contact Appropriate OEM Dealer or OEM Representative For Additional Information

Contents

Product Affected

Engine:

- L9 CM2350 L116B
- L9 CM2350 L123B
- L9 CM2350 L119B
- L9 CM2350 L116B

Original Equipment Manufacturer:

- Navistar

Chassis:

- 4300
- 4400
- HX.

Symptom:

- FC559
- Low Power

- Stage 1 fuel filter plugging

Issue

Root Cause:

- Racor® fuel filter element designed and released for 2017 shows a low service filter life caused by increased contaminants.

Verification

- Verify vehicle is equipped with Racor® fuel filter, Part Number 408114C1.

Resolution

- Reference Navistar® iKnow article: IK1500093.

Document History

Date	Details
2018-1-30	Module Created

Last Modified: 31-Jan-2018
