## Tech Tips

## TT 20-16-04

Date: November 25, 2016

## 2015-2016 Golf, GTI and Golf Sportwagen – Fuel Gauge Does Not Read Accurately after Performing the 20Y6 Update

If the fuel gauge is found to be reading inaccurate after performing the 20Y6 recall, please perform a capacitance discharge on the battery. Recheck fuel gauge for accuracy after the cap discharge has been performed.

© 2016 Volkswagen Group of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.