


Solution K72614548 Tuesday, March 6, 2018 5:42:05 PM CET

Solution

Solution	If P02FA is logged with no other codes or symptoms indicating a problem:
	there is No Fault Found (NFF)
Cause	US17 chassis may generate code P02FA, with Guided Diagnostics (GD) determining
Title (customer effect)	Diagnostic Trouble Code (DTC) P02FA Illuminating The Malfunction Indicator Lamp (MIL) - US17 (GHG17, Common Rail Fuel System) Chassis ONLY

If P02FA is logged with no other codes or symptoms indicating a problem:

- Verify the chassis emissions level
 - Details can be found in the Product Details box on the Product tab in PTT as seen below:



- Once the chassis is confirmed to be US17+OBD16 (Common Rail Fuel System):
 - Software improvements have been released to address P02FA. Reprogram the Engine Control Module (EMS). It is possible a warning box may open stating the current software is the same version. Select the option to reload the software if this occurs.

Solution visibility	Dealer distribution
Function(s)/compor	nent(s) affected
Function affected	DOC, DPF, 110 EMS, Diagnostic tool
Function Group	
Function Group	254 catalytic converter; exhaust emission control equipment , 258 emissions after-
	treatment , 28 ignition and control system
Customer effect	
Main customer effect	diagnostics/methodology, fault code/display
Fault code(s)	

Conditions	
Frequency of occurrence of problem	random
Administration	
Author	RU4469V
Dealer ID	RU4469V
Last modified by	RU4469V
Creation date	28-02-2018 15:02
Date of last update	28-02-2018 15:02
Review date	15-08-2018 00:08
Status	Draft copy
NA_MACK_Vehicle_R	
NA_MACK_Vehicle_Ran ge	Cabover, Conventional
NA_VOLVO_Vehicle_F	Range
NA_VOLVO_Vehicle_Ra	Conventional
Engine family	
Engine family	11L Engine, 13L Engine, MP7, MP8
Emission Standard	