

**\* \* TECHNICAL INFORMATION NOTICE \* \***

**DATE:** February 5, 2018  
**TO:** Mitsubishi Motors US & Puerto Rico Dealer Service and Parts Managers  
**RE:** Coolant Leaking from Water Hoses at CVT8 Fluid Cooler  
**TIN NO.** TIN-18-23-001

---

**AFFECTED VEHICLES:** 2016-18 Outlander equipped with 4 cylinder (2.4L) engine and CVT8 transmission (F1CJC/W1CJC)


**PURPOSE**

Dealers have reported coolant leaking from the water hoses at the CVT8 fluid cooler (see photo below). Normal dealer repairs have been to replace the water hose and/or clamps on the affected area.



(View looking up from the bottom of the vehicle)

In order to investigate this condition further, MMNA is looking to collect 5 complete sets of CVT8 fluid coolers with the water hoses and clamps **undisturbed**. Please do not remove the water hose clamps indicated by the circled areas in the photo below (the other hoses are for the CVT8 oil, not coolant). This is important since MMC needs to perform a duplication test to confirm the area of leakage.



Please open a Techline case, attach photos of the condition, and contact Techline (800-446-6064) to review the findings. Product Support will then contact the dealership to arrange return of the original parts to MMNA.

| <b>Part Description</b>         | <b>Part Number</b> |
|---------------------------------|--------------------|
| A/T Oil Cooler Assembly         | 2920A400           |
| T/M Oil Cooler Line Hose        | 2922B017           |
| T/M Oil Cooler Line Hose        | 2922B019           |
| T/M Oil Cooler Line Clip (17.8) | MU660005           |