

Tech Tip T-TT-0435-17

February 21, 2017

Subject		Market
Navigation Head Unit Precautions		USA
Service Category	Section	
Audio/Visual/Telematics	Navigation/Multi Info Displa	ıy
Applicability		
Toyota Navigation Head Units		

APPLICABLE VEHICLES

2010-2018	Camry	2011-2018	Highlander
2010-2018	Prius	2010-2018	Tundra
2010-2018	Sienna	2013-2018	Avalon HV
2010-2011, 2013- 2018	Land Cruiser	2012-2018	Prius V
2010-2018	4Runner	2010-2018	Sequoia
2011-2018	Avalon	2009-2016	Venza
2010, 2012-2015	Prius PHV	2010-2018	Tacoma
2012-2018	Prius C	2010-2018	Highlander HV
2010-2018	Camry HV		

CONDITION

This bulletin is regarding best practices when handling navigation systems that use Hard Disc Drive or Micro SD Card memory.

1. First type is generation 6 or 7 which utilizes HDD (Hard Disc Drive). Pioneer models that begin with **NXH**, have Map Data, Operating System and other Information in the Hard Disc Drive. With this system if a radio is being sent back for an exchange. The original Hard Disc Drive needs to be removed and installed into the newly serviced radio.






Navigation Head Unit Precautions

USA

Applicability

2. The Second type is Generation 8 Navigation system which utilizes the Micro SD Card. Pioneer models that begin with NXF, have map data in the Micro SD card. This is a customer accessible Micro SD card which can be found behind the front flip cover. The original Micro SD card should be removed and installed into the newly serviced radio.



The SD card is behind this flip cover. The Micro SD needs to be removed when returning the Main Unit to Pioneer.



RECOMMENDATIONS

There is another Micro SD card (*Operating System*) inside the Navigation Module. (Similar location to the Hard Disc Drive in the Generation 7 system). This micro SD Card Should Not be removed for any reason. Micro SD cards located in this internal slot need to be returned with the original radio.







This Micro SD card MUST NOT be removed.

This will void the Warranty status from Pioneer if removed and dealer will be debited the core credit.

TOYOTA	Tech Tip T-TT-0435-17		February 21, 2017
Subject		Market	
Navigation Head Unit	Precautions	USA	
Applicability			
_		_	

LINK REFERENCES

This Tech Tip does not contain any link references