ΤΟΥΟΤΑ	Tech Tip T-TT-0459-17	October 10, 2017	
Procedure	Length Too Long - Verification	Market USA	
Service Category Vehicle Exterior Applicability	Section Exterior Panels/Trim		
MY14-18 Tundra			
APPLICABLE VEHICLES			
2014-2018	Tundra		
CONDITION			
Some customers may experience Tailgate Cable Stay slack appearance. Tailgate Cable Stays are designed to have some slack when the Tailgate does not have a load applied, this is due to Tailgate loading requirements.			
	Stay length is OK - load the Tailgate in the area ad of \geq 23 lbs. (use Seatbelt Sensor Weight SS		
f Cablo Stay bas no slack/log	A REAL REAL REAL REAL REAL REAL REAL REA	functions as intended	
IT Cable Stay has no slack/loo	oseness, please inform customer part is OK and	I functions as intended.	
Expires on 10/10/2018 Ver. 28 01/01/2017T	© 2017, Toyota Motor Sales, USA	Page 1 of 2	

ΤΟΥΟΤΑ	Tech Tip T-TT-0459-17		October 10, 2017	
Procedure	ength Too Long - Verification	USA		
Applicability				
Link References				
This Tech Tip does not contain any	link references			

© 2017, Toyota Motor Sales, USA