	Tech Tip T-TT-	0315-14	November 05, 2016 Market
Clad Wheel (ervice Category	Chromtec) Servicing		USA
Suspension		section Tire/Wheel	
4-17MY Tundra,	Tacoma, Highlander/HV		
APPLICABLE VEHI	CLES		
2014-2017	Highlander	2014-2017	Tundra
2014-2017	Tacoma	2014-2017	Highlander HV
Condition	c clad) wheels are being dama	aged during mounting	and dismounting of tires.
efer to photos be	elow for identifying plastic and	aluminum portions of	wheel:
	Plastic		
	Aluminum		Plastic Aluminum
amage or crackin Ensure mo Ensure whe Use caution Ove	ered cone on tire changer, the ng to the plastic clad surface. unting surface of cone and wh eel is perfectly centered on tire n not to over-tighten cone or c r-tightening may cause plastic formation is needed, refer to ti	eel is clean of dirt and changer before tight lamp cladding to crack	d debris ening
INK REFERENCES	ot contain any link references		
xpires on 11/05/2	017 Rev1 © 2014, Toyo	ta Motor Sales, USA	Page 1 of

ΤΟΥΟΤΑ	Tech Tip T-TT-0315-14	November 05, 2016
Subject		Market
Clad Wheel (Chromtec) Servicing		USA
Applicability		

Т