



Service Bulletin

TECHNICAL

Subject: SIR/Airbag Light Illuminated, DTC B0081 (Passenger Presence System (PPS) Code) Stored (Inspect PPS System Connectors)

Models: 2006-2008 Chevrolet Cobalt, HHR
2009 Chevrolet Cobalt, HHR (SS Only)
2006 Pontiac Pursuit (Canada Only)
2007-2009 Pontiac G5

This bulletin has been cancelled. Please discard Corporate Bulletin Number 08-09-41-006D (Section 09 – Restraints).

For vehicles which may exhibit the condition above, please refer to SI for diagnostics.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION