

CAMPAIGN PARTS BULLETIN – FOR IMMEDIATE DISTRIBUTION

DATE	December 21, 2017	
то	Service Manager, Parts Manager	
CAMPAIGN(s)	SAFETY RECALL 69N1 – TAKATA SDI Driver Inflator	
MARKET(S)	United States & Canada	
PARTS INFORMATION	We are approaching the changeover period where certain, current (interim remedy) airbag inflators (listed below) will be replaced by final remedy parts.	
	Over the coming weeks, you will see a decrease in the supply and allocations of these interim remedy inflators. Dealers scheduling repairs under this recall should take this into consideration and only schedule customer appointments according to available internal (interim remedy) parts inventory. Future communications will follow with additional details and actions your dealership will need to take as we move towards launching final remedy repairs.	
	Recall Code: 69N1	
	Part Number	Models
	8R0 898 201	Audi Q5
	8R0 898 201 A	Audi Q5
	8F0 898 201	Audi A5 Cabriolet

IMPORTANT REMINDER ON VEHICLES AFFECTED BY SAFETY & COMPLIANCE RECALLS

<u>New Vehicles in Dealer Inventory:</u> It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.

<u>Pre-Owned Vehicles in Dealer Inventory:</u> Dealers should not deliver any pre-owned vehicles in their inventory which are involved in a safety or compliance recall until the defect has been remedied.