



Service Bulletin

File in Section: -


Bulletin No.: 17-NA-334

Date: October, 2017

INFORMATION

Subject: Information on Diesel Engine Soot Deposits at the Variable Turbine Geometry (VGT) Pin

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Cruze (Gen II - VIN B)	2017	2018			Diesel (RPO LH7)	
	Equinox						
GMC	Terrain	2018	2018				

Involved Region or Country	North America
Condition	 <p style="text-align: right; font-size: small;">4879702</p> <p>Some customers may comment that combustion deposits or soot (1) can be seen coming from the Turbo Actuator Pin/Arm (2).</p>
Information	<p>This is normal operation and will not affect the function of the Turbocharger. There is a small gap between the seal and the shaft to allow for proper rotation.</p> <p>Do Not replace the Turbocharger.</p>

Parts Information

No parts are required for this repair.

Version	1
Modified	Released October 18, 2017

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION