

Audio 20: Surround sound setting with sound system (code 810) is not stored after an ignition cycle

Topic number	LI82.60-P-067426
Version	1
Function group	82.60 Radio, audio, video systems
Date	12-06-2017
Validity	MODEL 205, 253 with code: 520/522, 154, 810
Reason for change	
Reason for block	

Complaint:

If a custom surround sound setting has been set, the central display shows the surround sound setting "Front" after an ignition cycle.

See attachment.

Note:

The surround sound setting is stored. The custom setting is shown incorrectly in the central display.

Attachments	
File	Description
Raumklangeinstellung_zentral.jpg	Selected surround sound setting
Raumklangeinstellung_vorn_1.jpg	Surround sound settings after ignition cycle

Cause:

Possibly software release of Audio 20 control unit (A26/17).

Remedy:

Perform software update of Audio 20 control unit (A26/17) (the software is estimated to be available with Regio DVD 03/2018).

Symptoms
Communication/information / Entertainment / Audio/Sound / Tone setting malfunction

Control unit/fault code		
Control unit	Fault code	Fault text
A2 / A40/3 / A26/17 - Audio or COMAND, A40/3 / A26/17 - Audio or COMAND (Audio) (HU5)	-	-

XENTRY TIPS

Attachments

Raumklangeinstellung_zentral.jpg:



Raumklangeinstellung_vorn_1.jpg:



XENTRY TIPS
