

XE
XF

TCU Water
ingress

Recent investigations into root cause of some TCU failures on XE and XF models have uncovered a water ingress concern, due to poor sealing at the Center High Mounted Stop Lamp.(CHMSL) A communication is being prepared, but any XE or XF should be checked for water ingress past the CHMSL gasket as possible root cause for TCU failure.

TBD