

Dash Center Vent Damaged/Broken

Topic number	LI83.10-N-067607
Version	1
Function group	83.10 Ventilation
Date	01-23-2018
Validity	Metris 447.603/.703
Reason for change	
Reason for block	

Complaint:

Customer complains the center vents on the dash board have broken fins/control knobs.

Attachments	
File	Description
Center Vent Damage.JPG	Center Vent Damage
Center Vent Damage 2.JPG	Center Vent Damage 2

Cause:

Center air vent with broken fins and knob controls are a result of improper operation, abuse, or incidental damage.

Remedy:

Replacement of the air vent.

Note: Replacement parts and labor are not covered under warranty. Please refer the customer to the owners manual section "Adjusting the air vents" for coaching.

Symptoms
Body / Air conditioning / Heater / Center air vent does not close

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 447 830 00 54			Air Nozzle	1		X


WIS-References			
Document number	Title	Note	Allocation
AR83.10-S-4503EE	Remove and install center air vent		Remedy

XENTRY TIPS

Validity		
Vehicle	Engine	Transmission
Vito/Metris 447 - 447.603	*	*
Vito/Metris 447 - 447.703	*	*

Attachments

Center Vent Damage. (1) Parts missing / (2) adjustment knob not attached
JPG:



Center Vent Damage 2. (3) Scratches caused by loose parts
JPG:

