

## Fault Code P089300 on 722.9 Transmission with VGS4NAG2

Topic number	LI27.00-P-060097
Version	1
Design group	27.00 General
Date	10-28-2014
Validity	All vehicles with transmission 722.9 and control unit variant VGS4NAG2
Reason for change	
Reason for block	

**Complaint:**

Vehicle in limp-home mode with fault code P089300. Normal operation returns after key cycle.

**Cause:**

Under investigation

**Remedy:**

Please create a PTSS case with the following data

- Quicktest with freeze frame data
  - EEPROM in \*.log file format
  - VGS Control unit log
- Front line agent will respond to the case

<b>Symptoms</b>
Power transmission / Automatic transmission / Automatic transmission - function / Limp-home mode

<b>Control unit/fault code</b>		
Control unit	Fault code	Fault text
VGS - Fully integrated transmission control (Y3/8n4) (VGS4NAG2)	P089300	Hydraulic fault in transmission

<b>Validity</b>			
	Vehicle	Engine	Transmission
	C (205)	*	722
	CLS (218)	*	722
	E (212)	*	722
	GL (166)	*	722

# XENTRY

M (166)	*	722
S (217)	*	722
S (222)	*	722
SL (231)	*	722