

Liftgate protective film wrinkled

Topic number	LI72.20-P-064479
Version	1
Design group	72.20 Rear door, tailgate
Date	07-11-2016
Validity	Model series 190 coupe
Reason for change	
Reason for block	

Complaint:

Body-side protective film for liftgate trunk lid lifter wrinkled, kinked, displaced, bubbled

Attachments	
File	Description
Picture1.jpg	Area of interest

Cause:

Assembly error

Remedy:

Open liftgate and check left/right protective film for correct seating and clean bonding. Remove protective film if necessary. To do so, clean area with Teroson A0059891971 PU8550 and attach new film.

Symptoms
Body / Door/Flap / Hood/flap / Trunk lid/liftgate / Seal deformed

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 190 983 02 83			Right protective foil	1		X
A 190 983 01 83			Left protective foil	1		X

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			75A05 **	
			75N05 **	

Attachments

XENTRY TIPS

Picture1.jpg:

