

LED Intelligent Light System inoperative

Topic number	LI82.10-P-063698
Version	2
Design group	82.10 Exterior lights
Date	04-08-2016
Validity	Model X253
Reason for change	Damage codes added
Reason for block	

Complaint:

LED Intelligent Light System inoperative - Fault message in instrument cluster

Fault code: B284D71

The actuator motor in the headlamp for the light distribution has a malfunction.

The actuator is blocked

Cause:

Incorrect sensor position stored in parameterization in control unit.

Remedy:

Perform SCN coding of headlamp control unit.

Symptoms
Overall vehicle / Lighting / Exterior lights / Driving lights / Active curve illumination / Nonfunctional

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			87A0Y 90	
			87N0Y 90	