

Vehicles equipped with Flexray and 8HP Trans.

A customer may complain of a gearbox warning lamp, or restricted performance message.

Diagnosis finds DTC P0715-64 "Input/Turbine Shaft Speed Sensor "A" Circuit - Signal plausibility failure" stored in the TCM. Should you encounter this condition, please raise a TA for diagnostic assistance. Include in your submission a session file, adaptation data read out from the vehicle and a picture of a fluid sample.

Under Investigation