



# Service Bulletin

File in Section: -


Bulletin No.: 18-NA-117

Date: April, 2018

## INFORMATION

**Subject: Foam Visible Where Instrument Panel Meets Windshield**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Cruze	2017	2018				

<b>Involved Region or Country</b>	North America and N.A. Export Regions
<b>Condition</b>	 <p style="text-align: right; font-size: small;">5042338</p>
<b>Cause</b>	This condition may be caused by the foam that is installed on the instrument panel to aid with eliminating squeaks and rattles.
<b>Correction</b>	No repairs are to be attempted. The foam is visible to design intent.

<b>Version</b>	1
<b>Modified</b>	Released April 16, 2018

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION**