



Bulletin No.: PIP4600F
Published date: 03/1/2017

Preliminary Information

PIP4600F TAC 2ML70 (Two-Mode Hybrid) Transmission Restriction has ended

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade	2009 - 2013	All	All	All	M99
Chevrolet	Silverado	2009 - 2013	All	All	All	M99
Chevrolet	Tahoe	2008 - 2013	All	All	All	M99
GMC	Sierra	2009 - 2013	All	All	All	M99
GMC	Yukon	2008 - 2013	All	All	All	M99

Supersession Statement

This PI was superseded end the parts Restriction. Please discard PIP4600E.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

Effective 3/1/017 the 2ML70 Transmission Assembly is now off a GM TAC (Technical Assistance Center) Restriction .

Note: The 2ML70 Transmission is considered serviceable for the majority of all service repairs. Dealers should do a repair vs. replace cost comparison.

Recommendations / Instructions

Engineering would like to thank all dealers that participated in this Exchange program.

Thanks to your participation

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



©2016 General Motors. All Rights Reserved.