

Technical Service Bulletin

PSS 91 Bang & Olufsen: Subwoofer settings missing from MMI tone settings menu

91 18 82 2050585/1 March 5, 2018.

Model(s) Year	VIN Range	Vehicle-Specific Equipment
A3, A4, 7 and Q	2017	All	MIB2 High Navigation

Condition

Customer states:

 The subwoofer adjustment is missing in the MMI for vehicles equipped with Bang & Olufsen (PR Code 9VS) and the customer vehicle has MMI Navigation (PR Code 7UG).

0
0
ontrol 0
ontrol

Figure 1. Sound settings missing Subwoofer option.

Technical Background

There is known MMI software concern which prevents the subwoofer setting from being present in the MMI sound settings menu.

Production Solution

Software solution introduced into series production starting CW22/17.

Service

For cars with Navigation, currently there is no service solution available (a software update will be released to fix this concern). Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *App Links >> Service >> Pending Service Solutions (PSS)*), or through the Technical Assistance page in Elsa.

© 2018 Audi of America, Inc.

Page 1 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

For cars without Navigation and with Bang & Olufsen (PR Codes 7UH & 9VS), a service solution is available see TSB 2050567: 91 Bang & Olufsen: Subwoofer settings missing from MMI tone settings menu.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

• TSB 2050567, 91 Bang & Olufsen: Subwoofer settings missing from MMI tone settings menu.

All parts and service references provided in this TSB (2050585) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2018 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

© 2018 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.