



Service Bulletin

PRELIMINARY INFORMATION

Subject: Diagnostic Tip for Coolant Leak at Oil Cooler Inlet Pipe O-Ring After Service Engine Replacement

Models: 2001-2010 Chevrolet Silverado
2003-2010 Chevrolet Kodiak
2006-2010 Chevrolet Express
2001-2010 GMC Sierra
2003-2010 GMC TopKick
2006-2010 GMC Savana
Equipped with Duramax Diesel Engine (RPOs LB7, LLY, LBZ or LMM)


Condition/Concern

Technicians may find a coolant leak coming from the oil cooler inlet pipe after a service engine replacement. Some Duramax® service engines may have been assembled with a cut oil cooler inlet pipe O-ring.

Recommendation/Instructions

Inspect the oil cooler inlet pipe and replace the O-ring if any leaks are found.

The following engine serial numbers are affected. The serial number can be found on the bottom right side of the block. Refer to the picture below.



Engine Serial Numbers						
B1423416696	B1422516676	B1423416693	B1422516664	B1425316790	B1424816734	B1428716867
B1423416698	B1422516677	B1423416694	B1422516665	B1426916802	B1424816735	B1428716868

B1423416700	B1422516678	B1425316767	B1422516666	B1428716881	B1424816736	B1428716869
B1423416704	B1422516679	B1425316768	B1422516667	B1424116711	B1424816737	
B1425316740	B1422516680	B1425316769	B1425316777	B1424116713	B1424816738	
B1425316741	B1422516681	B1425316770	B1425316778	B1424116715	B1428216846	
B1425316743	B1422516682	B1425316771	B1425316779	B1424116716	B1428216847	
B1425316746	B1422516683	B1425316772	B1425316780	B1424116717	B1428216848	
B1425316749	B1422516684	B1425316773	B1425316781	B1424116721	B1428216849	
B1422516668	B1422516685	B1425316774	B1425316782	B1424816726	B1428216841	
B1422516669	B1422516686	B1425316775	B1425316783	B1424816727	B1428216844	
B1422516670	B1422516687	B1425316776	B1425316784	B1424816728	B1428716853	
B1422516671	B1422516688	B1427416809	B1425316785	B1424816729	B1428716860	
B1422516672	B1422516689	B1427416813	B1425316786	B1424816730	B1428716861	
B1422516673	B1422516690	B1427416817	B1425316787	B1424816731	B1428716862	
B1422516674	B1422516691	B1424816725	B1425316788	B1424816732	B1428716863	
B1422516675	B1422516692	B1422516663	B1425316789	B1424816733	B1428716866	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION