

GPOP - Issue Review System

Part Number: RL305553A\$, RL305552A\$, RL305551A\$, RL304730A\$, RL304723A\$,
RL304305A\$, RL304304A\$, RL304087A\$, RL304086A\$, RL304085A\$,
RL304084A\$, RL304083A\$, RL304082A\$, RL304081A\$, RL297902A\$,
RL297901A\$, RL297900A\$, RL297895A\$, RL297894A\$, RL295831A\$,
RL295830A\$, RL292315A\$, RL285843A\$, RL282814A\$, RL277659A\$,
RL277658A\$, RL277273A\$, RL277272A\$, RL277271A\$, RL277270A\$,
RL276816A\$, RL276815A\$, RL273050A\$, RL273049A\$, RL273046A\$,
RL273045A\$, RL273044A\$, RL273041A\$, RL271651A\$, RL265912A\$,
RL265789A\$, RL260065A\$, RL260064A\$, RL260063A\$, RL260062A\$,
RL260061A\$, RL260059A\$, RL260051A\$, RL257269A\$

Part Description: 9-spd Transmission

Issue Description: FOR NAFTA Market Only: If you are ordering this transmission please follow all wiTECH pop ups and Warranty Payment Guidelines. If this vehicle contains 1 of the 30 Diagnostic Codes in the 9 Speed Tutorial located on the Service Home Page then please follow the repair steps and submit a Topology report as well as a Vehicle Scan Report with the Warranty Claim.~

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
