

9003216

03/08/2017

MY14, 15, 16, 17

D2, DJ, DS

GPOP - Issue Review System

Part Number: 5RR541XRA\$, 5RR551XRA\$, 5RR791ARA\$, 5RR791AUA\$, 5RR791BUA\$, 5RR791CLA\$, 5RR791R3A\$, 5RR791R4A\$, 5RR791RVA\$, 5RR791S2A\$, 5RR791W7A\$, 5RR791XRA\$, 5XY521ARA\$, 5XY521AUA\$, 5XY521BUA\$, 5XY521CLA\$, 5XY521R3A\$, 5XY521R4A\$, 5XY521RVA\$, 5XY521S2A\$, 5XY521W7A\$, 5XY521XRA\$, 68263849A\$, 68231241A\$, 68231242A\$, 68231243A\$

Part Description: Power Fold Rearview Mirror

Issue Description: Prior to replacing this part for a loose mirror, please first follow this procedure to reset the pivot mechanism. Move the mirror to its full forward position and then to full retract position using the power fold mirror button located on drivers side door panel. Perform this procedure three times. If this doesn't resolve the issue, then repair as necessary.~

Note:

1- The looseness of power fold mirror does not necessary indicate a defective mirror, it may be caused by folding it manually rather than using the power fold feature. If the mirror is adjusted manually out of the proper detent, always use the button to adjust it back into sync.~

2- The intended use of the power fold mirrors is by pushing the button to fold and unfold the mirror. Only manually fold the mirrors when absolutely necessary.~

3- In the circumstance where the left hand mirror and right hand mirror are in different positions, it may take up to three cycles (bottom pushes) to re-sync the mirrors together.

~_____~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
