

GPOP - Issue Review System

Part Number: 5XY27DX9A\$, 5XY271L1A\$, 5XY26DX9A\$, 5XY261L1A\$, 5ME45DX9A\$, 5ME451L1A\$, 5ME44DX9A\$, 5ME441L1A\$, 5ME391L1A\$, 5ME39DX9A\$, 5ME391T5A\$, 5ME39BD3A\$, 5ME381L1A\$, 5ME38DX9A\$, 5ME381T5A\$, 5ME38BD3A\$, 5KP791DVA\$, 5KP791X9A\$, 5KM49DX9A\$, 5KM491X9A\$, 5KM48DX9A\$, 5KM481X9A\$, 5KC792X9A\$, 5KC791XRA\$, 5KC671X9A\$, 5KC661X9A\$, 1VL09DX9A\$, 1VL09HL1A\$, 1VL09LC5A\$, 1VL09LU5A\$, 1VL08DX9A\$, 1VL08HL1A\$, 1VL08LC5A\$, 1VL08LU5A\$, 1VL07LU5A\$, 1VL071R9A\$, 1VL071S4A\$, 1VL061R9A\$, 1VL061S4A\$, 1UL39DX9A\$, 1UL391X9A\$, 1UL38DX9A\$, 1UL381X9A\$, 1SY99DX9A\$, 1SY991X9A\$, 1RN02DX9A\$, 1RN021X9A\$, 1RJ431XVA\$, 1RJ431X9A\$, 1RJ432X9A\$, 1RH751X9A\$, 1RH741X9A\$, 1RH741XVA\$, 1RH07XXXA\$, 1PK56BD3A\$, 1PK56DX9A\$, 1PK56GT5A\$, 1PK56HL1A\$, 1LQ45DX9A\$, 1LQ451DVA\$, 1LQ44DX9A\$, 1LQ441DVA\$, 1HZ141T5A\$, 1HZ141L1A\$, 1GQ92BD3A\$, 1GQ92DX9A\$, 1GQ92GT5A\$, 1GQ92HL1A\$, 1GQ92LC5A\$, 1GQ92LU5A\$, 1GP44BD3A\$, 1GP44DX9A\$, 1GP44GT5A\$, 1GP44HL1A\$, 1GE37BD3A\$, 1GE37DX9A\$, 1GE37GT5A\$, 1GE37HL1A\$, 1GE13BD3A\$, 1GE13DX9A\$, 1GE13HL1A\$, 1GE13LC5A\$, 1GE13LU5A\$, 1GE12BD3A\$, 1GE12DX9A\$, 1GE12HL1A\$, 1GE12LC5A\$, 1GE12LU5A\$, 1BY491DVA\$

Part Description: Restraints

Issue Remove I-Sheet from packaging. Correct information sheet (I-Sheet) has been
Description: added to Star Parts. Print I-Sheet for technician use.

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
