

5/4/2016 MY 13, 14, 15, 16 RT

GPOP - Issue Review System

Part Number: 1FL68dx9A\$, 1FL68hI5A\$, 1FL68BD5A\$, 1FL69dx9A\$, 1FL69hI5A\$, 1FL69BD5A\$

Part Description: Flipper Close Out panel

Issue Description: The flipper panel close out located in the rear by the load floor is failing. Engineering is collecting data on the nature of these failures for future design robustness. Please contact Deepak Patil at cell (303) 802-9794 with the details (call / text (photo)/ voicemail). email - deepak.patil1@fcagroup.com. If there is no response within 15 minutes please proceed with the repair.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
