

- ATTENTION:**
- GENERAL MANAGER
  - PARTS MANAGER
  - CLAIMS PERSONNEL
  - SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.


©2018 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

## SERVICE BULLETIN

**APPLICABILITY:** 2003-2012MY Legacy & Outback  
 2002-2011MY Impreza  
 2003-2013MY Forester  
**2002-2014MY WRX**  
**2004-2017MY STI**  
 All models listed with 4-cylinder “EJ” Engine Type

**NUMBER:** 02-172-18R

**DATE:** 02/01/18

**REVISED:** 02/06/18

**SUBJECT:** Oil Seepage- New Oil Filler Tube O-Ring

**INTRODUCTION:**

This bulletin provides details regarding a new oil filler tube o-ring developed to address engine oil seepage concerns. This seepage may accumulate along the bottom sealing surface of the rocker cover. The new o-ring utilizes material which has an increased resistance to engine heat.



**PRODUCTION CHANGE INFORMATION:**

On WRX STI models, the new o-ring was incorporated into production starting with VIN H9825652.

**PART INFORMATION:**

The part number for the new o-ring is: **806922120**.

**NOTE:** In some cases where the oil fill tube (DUCT) is being replaced, part numbers 15250AA062 and 15250AA041 include the new o-ring.

**SERVICE PROCEDURE / INFORMATION:**

When replacing the o-ring and / or filler pipe, follow the procedure outlined in the applicable Service Manual.

**REMINDER:** The o-ring is one-time use and **must** be replaced whenever the oil filler pipe is removed.

*Continued...*

**CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.**

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

**Subaru of America, Inc. is ISO 14001 Compliant**

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

**WARRANTY / CLAIM INFORMATION:**

For vehicles within the Basic New Car Limited or Powertrain Limited Warranty period or covered by an active Subaru Added Security Powertrain, Classic or Gold plan, this repair may be submitted using the following claim information:

Labor Description	Labor Operation #	Labor Time	Fail Code
OIL FILLER TUBE / O-RING R&R	A244-111	0.2	AAJ-34

**IMPORTANT REMINDERS:**

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.