

| | |
|----------------------|---|
| Reference | SSM73030 |
| Models | F-PACE / X761 XE / X760 XF / X260 |
| Title | Ingenium I4 2.0L Diesel - Logging P062F-44 - EEPROM Error |
| Category | Engine |
| Last modified | 30-Jan-2017 00:00:00 |
| Symptom | 499000 Basic Engine |

Content**Issue:**

JLR are investigating X260/X760/X761 INGENIUM I4 2.0L Diesel Powertrain control module (PCM) logging DTC **P062F- 44** - EEPROM Error.

Cause:

Unknown at this time.

Action:

Any retailer who find an issue with INGENIUM I4 2.0L Diesel PCM's logging DTC P062F- 44 EEPROM Error please **DO NOT CLEAR THE DTC** and It would be appreciated if no further diagnosis is undertaken, an EPQR is submitted and an email is sent to thooper2@jaguarlandrover.com to investigate the issue first hand.

Thank you in advance for your assistance in this matter.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.