

9003118

07/16/2014

MY13-14

RT

GPOP - Issue Review System

Part Number: 1LW35BD1A\$, 1UU41HL5A\$, 1UU41LTUA\$, 1UW06LTUA\$, 1UW10LTUA\$,
1UW13DX9A\$, 1UW13HL5A\$, 1YK23HL5A\$, 1YK24HL5A\$, 5SF67HL5A\$

Part Description: Sliding Door Trim Panel

Issue Description: If a contact condition with the exterior quarter panel occurs, please engage the dual lock in the center of the trim to the door inner module.

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.